

GREGORY S. BELL Lieutenant Governor

Mine Name: Golden/Lucky Chance

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Inspection Report Minerals Regulatory Program

April 28, 2010

	18219
Reviewed:	1/1//
	,

Permit Number: S/037/0064

Operator Name: Dan Shumway	Inspection Date: April 14, 2010		
Inspector(s): T Munson	Time: 4-5 PM Mine Status: regraded		
Other Participants: none			
Elements of Inspection	Evaluated	Comment	Enforcemen
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Reclamation Backfilling/Grading (trenches, pits, roads, highwalls, shafts) Soils 			
9. Revegetation	Ti .		i i

Bond Amount: \$0.00 Fees: fees not paid since 2008

Purpose of Inspection: To determine if regrading had been completed and the site cleaned up.

Inspection Summary:

I drove close to the site and had to walk the last hundred yards. The site consists of two piles of regraded dirt approximated 50 by 100 feet in size. The surrounding area is completely overgrown with riparian vegetation and it will be a very short time before these piles are overgrown as well. In conversations with Paul Baker of DOGM and Ted McDougall of the Monticello BLM, it was decided we could release this site and close this permit. The size of the actual disturbance and the area's potential to reclaim itself, dictate this decision, as well as, the relative inaccessibility of this site.

Photos were taken to document site conditions.

Conclusions and Recommendations:

The Division can close this permit with BLM concurrence. No bond exists to return to the operator.

Inspector's Signature

TM:vs

cc: ted_mcdougall@blm.gov

Dan Shumway, 977 East Kiva Drive, Blanding, Ut 84511

O:\M037-SanJuan\S0370064-Golden-LuckyChance\inspections\insp04142010.doc



